This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

UK Patent Application (19) GB (11) 2 091


- (21) Application No 8200688
- Date of filing 11 Jan 1982 (22)
- **Priority data** (30)
- 8100780 (31)
- 12 Jan 1981 (32)
- United Kingdom (GB) (33)
- Application published (43)28 Jul 1982
- (51) INT CL3
- B23P 6/00
- Domestic classification **B3A** 166
- Documents cited None
- (58) Field of search **B3A**
- (71) Applicants Refurbished Turbine Components Limited, George Baylis Road, Droitwich, Hereford and Worcester.
- (72) inventors Michael James Fraser
- (74) Agents Forrester, Ketley & Co., Rutland House, 148, Edmund Street, Birmingham, B3 2LD.


(54) Turbine blade repair


(57) A method of repairing a turbine blade (10) of the type having one or more lacing wire holes (20, 21) comprising the steps of welding additional metal (17) to the blade (10) and subjecting the blade (10) to a stress relieving heat treatment process before which the or each lacing wire hole (20, 21) is effectively eliminated by filling the hole or holes (20, 21) with material the same as or at least compatible with the material from which the blade is made. The turbine blade (10) may be subjected to the application of mechanical forces to restore its form and machined to restore its shape and may be gauged to ensure both its form and shape is correct.





W














SPECIFICATION

Am thod of reparing turbine blad s

5 The present invention relates to a method of repairing turbine blades.

Repairing turbine blades by welding is in some cases a highly satisfactory method of effecting a repair and is considerably cheaper than total re10 placement of the blade.

It has been found however that the repair of some turbine blades by methods using a welding process is not satisfactory since even though from visual inspection the repair appears satisfactory, problems 15 can still arise because turbine blades are in use subjected to considerable forces.

The type of turbine blade assembly, which may comprise a rotor or a stator, in which a repair by welding has been found to be not satisfactory is that 20 in which adjacent blades are interconnected, usually in the region of their outer ends by snubbers, lacing wires or other members requiring a hole or other discontinuity to be formed in the turbine blade (all such members being hereinafter referred to for 25 convenience as lacing wires and the discontinuities as lacing wire holes). The purpose of the lacing wires is to prevent excessive relative movement between the blades and to generally dampen any vibration during operation of the turbine. Such lacing wires 30 therefore render the turbine structure more rigid but do not prevent all relative movement between the blades.

Since the outer end of the turbine blade in a rotor assembly is the part which has the greatest linear 35 speed in use, it is the outer end that is most prone to erosion. Erosion generally occurs because of contact between the turbine blades with particles carried by the steam and also with the steam itself.

At the high pressure end of a steam turbine for 40 example, the blades are generally subjected to damage from particles of solid matter carried by the steam due to contact between the blades and the particles, and since the rate of erosion will be dependant on relative speeds between the blades 45 and particles, it is generally the leading edge at the outer end of each blade that is most prone to erosion by impact between the particles and said edges.

At the low pressure end of the turbine, the steam is at a lower temperature having been cooled during 50 passage through the turbine and water condenses therefrom more readily. The steam is therefore wetter and the transfer of energy by impact on the turbine blade of the steam itself is greater at the low pressure end of the turbine than that at the high 55 pressure end. Here again it is predominantly the outer ends of the blade which are esp cially subject to erosion.

It is known to form the leading edge at the outer end of the turbine blade as an insert from a different 60 material from that used for the remainder of the blade. Turbine blades are often made from a chrome steel and the insert may be made from stellite or a suitable hardened steel, in which case the insert may be brazed to the blade. If the blade has not originally 65 been formed with such an insert and is subsequently

required to be repaired, the turbine blade may then have such an insert introduced. In which case, th insert may be secured to the remainder of the turbine blade by a welding process, the blade end 70 being subsequently machined to restore it to its original form.

Such a method of repairing turbine blades has been found to be successful only in the case where the turbine blade is a uniform or homogeneous structure and, in the case of turbine blades having discontinuities such as lacing wire holes, then even though the welded repair may have the appearance of being satisfactory, in use such blades are prone to "stress corrosion cracking" which leads to a short and hence unacceptable life after repair.

It is an object of the present invention to provide a method of repairing turbine blades of the type having lacing wire holes, which method enables a welding process to be used satisfactorily.

According to the present invention, we provide a method of repairing a turbine blade of the type having one or more lacing wire holes, the method comprising the steps of welding additional metal thereto, machining the repaired blade to the required shape and subjecting the blade to a stress relieving heat treatment process, wherein prior to the heat treatment process, the or each lacing wire holes is effectively eliminated by filling the hole or holes with material which is the same as or at least is compatible with the material from which the blade is made and reforming, after the heat treatment process, the or each of the holes.

The filling of the lacing wire holes may be effected at any stage of the repairing method prior to heat treatment process and, is preferably carried out at the same time as the addition of metal by welding.

It will be understood that since the plugs have only a temporary function to perform, it is contemplated that they need not always be made of the same

105 material as that of which the blade itself is made. Such plugs do, however, have to be capable of performing the required function, namely maintainence of the condition of the metal of the blade around the holes during the heat treatment in a state

110 such as to avoid the tendency to local crack formation in subsequent service. The term "compatible" is used herein to identify such other material.

In selection of a compatible material consideration should be given to materials which have properties such as the thermal coefficient of expansion, and an ability to successfully bond or fuse welding or brazing to the material of the blade.

Machining of the blade may be carried out before or after the heat treatment process provided the 120 machining does not generate heat in sufficient quantities to bring about residual stress in the turbine blade.

It may be that during the addition of metal by welding during the method of repairing the turbine 125 blade, distortion of the blade will occur, and the blade may therefore after the addition of metal be subjected to mechanical forces to return the blade to its original shape. Said subjecting of the blade to mechanical forces preferably takes place before said heat treatment process such that the heat treatment

2

is ffective to eliminate any stress in the turbine blade and is preferably carried out after filling of the lacing wire holes in order to eliminate the possibility of causing damage in the region of the lacing wire holes by the application of mechanical forces.

It is essential that the turbine blade is returned to its original shape and form and to ensure that the repaired article is exactly the shape and form required, preferably a gauging step is included in 18 said method.

One reason for the need to fill and subsequently reform the lacing wire holes is believed to be that even though the lacing wire holes may not be in an area which is eroded and hence in an area which as such is in need of repair, the heating and consequent stressing of the turbine blade caused by the repair in other adjacent areas, and subsequent heat treatment and possible mechanical stressing, affects the structure of the material in the vicinity of or around the lacing wire holes and thus increases the risk of crack formation leading to subsequent failure of the

formation leading to subsequent failure of the turbine blade.

It is further believed that the phenomenon of "stress corrosion cracking" occurring in use around

25 the lacing wire holes may be due to concentration of residual stress in the region of the lacing wire holes during application of mechanical forces to the turbine blade, it being necessary to maintain or return the blade to its correct shape after repair.

30 Preferably therefore, where substantial mechanical forces have been applied to the turbine blade to return the blade to its correct form during repair, the lacing wire holes will have been filled prior to the application of such mechanical forces.

The lacing wire holes may be filled by introduction of the welding metal itself or introduction of a new piece of solid state material welded into the hole. In both cases the lacing wire holes will be filled at least before heat treatment.

The invention will now be described in more detail by way of example only with reference to the accompanying drawings wherein:-

Figure 1 is a cross-section view looking radially inwardly of three turbine blades interconnected by 45 lacing wires;

Figure 1A is a prespective view of a complete turbine rotor;

Figure 2 is a view of an end region of the turbine blade illustrating the area where erosion is most 50 common;

Figure 3 is a cross-section of the turbine blade taken along the line A-A shown in Figure 2;

Figure 4 illustrates a welding process being used to repair a turbine blade;

55 Figure 5 is a cross-section along the line B-B shown in Figure 4;

Figure 6 illustrates an alternative repair involving by a welding process;

Figure 7 is a cross-section along the line C-C 60 shown in Figure 6:

Figure 8 illustrates a repaired turbine blade; Figure 9 is a cross-section along the line D-D shown in Figure 8;

Figure 10 is a view of a turbine blade in an 65 apparatus to subject the blade to mechanical forces

in order to return it to its required f rm;

Figure 11 is a schematic view illustrating the turbine blade in a furnace of heat treatment;

Figure 12 is a perspective view of a gauge 70 apparatus;

Figure 13 is a plan view of the gauge apparatus shown in Figure 12.

Referring first to Figures 1 and 1A, three turbine blades are shown 10, 11 and 12, each turbine blade 75 having through bores 13 and 14 through which pass respective lacing wires 15 and 16.

The lacing wires 15 and 16 can pass either with clearance through their respective through bores 13 and 14 in the turbine blades, or may be joined to 80 each turbine blade by welding for example.

If the lacing wires pass freely through the through bores 13 and 14 in use of the turbine, the radially outwardly directed centrifugal force on the lacing wires between adjacent turbine blades will cause pressure contact between the lacing wires and the turbine blades, such pressure contact being sufficient to provide the required restriction of relative movement between adjacent turbine blades.

Figure 1A illustrates an example of a rotor from a 90 turbine, the three turbine blades 10, 11 and 12 shown in Figure 1 being three of a considerable number of blades forming the complete array in the rotor.

The turbine blades, such as those shown at 10, 11, 12, can be made from a variety of materials depending on the function and operating conditions of the turbine. A typical material from which a blade in a steam turbine may be manufactured is chrome steel being approximately 12% chrome.

Referring now to Figure 2, the area of the turbine
100 blade which is most prone to erosion is illustrated,
this being the leading edge 17 of the outer end of the
turbine blade since it is this part of the blade which
"collides" with the steam or particles carried thereby
during use of the turbine, and which also has the
105 greatest linear speed being the radially outermost
point from the axis of rotation. The leading edge 17
is the edge which is nearest the steam inlet end of
the turbine.

Figure 3 illustrates the area where erosion is most 110 likely to occur on the leading edge 17 of the turbine blade 10, and which erosion even through it may be severe, is not normally so extensive as to reach as far as the nearest lacing hole 13.

Referring now to Figures 4 to 11, a method of 115 repairing the turbine blade in accordance with the invention will now be described.

A piece of material is cut out from the margin bordering the leading edge 17 and a new piece 18 of hard material, such as Stellite, is welded to the remainder of the turbine blade 10. The material used for welding is one able to form a welded function with the material from which the blade is made, for example, 12% chrome steel and the material, Stellite, which is to be welded to the turbine blade 10. A suitable welding material is 12% chrome steel.

The lacing wire holes 13 and 14 are filled by welding in plugs 20 and 21 which may be of the same material from which the turbine blade is made, i.e. 12% chrome steel, and one again a suitable 130 welding metal will be used to secure these plugs in

position.

In Figures 6 and 7 an alternative repair is shown in which the turbine blade 50 has the leading outer edge region 57 repaired by the addition of fused 5 metal by a welding process. The lacing wire holes 52 and 53 are likewise filled with fused metal. The method of repair then continues in an identical manner as that described for the blade 10 shown in Figures 4 and 5.

All eroded material now having been replaced, the excess material may at this stage be machined to restore the blade to its proper shape or provided that the machining does not unduly raise the temperature of the turbine blade, the machining can be 15 carried out at a later stage in the repair process.

If the turbine blade 10 has not significantly altered its form, then the next stage in the repair process is to heat the blade to a predetermined temperature to relieve any residual stress in the blade.

Referring to Figure 11, the heat treatment may be carried out in any suitable oven 60, the temperature to which the blade is heated and the time to which it is subjected to such heat, depending on the size of the turbine blade and the material from which it is 25 made. A typical heat treatment for a blade made from a 12% chrome steel being 1 hour at 660°C.

It is quite common that following removal of part of the blade as shown in Figures 4 and welding in of the new piece 18 of hard material such as Stellite, the 30 form of the blade can be altered by distortion, which form must be connected prior to heat treatment.

The reforming of the blade may involve the step of causing a twisting of the blade between its ends and a simple apparatus for carrying out such twisting is 35 illustrated in Figure 10.

The root end 24 is held in a vice 25 and the other end 26 is held in a second vice 27 which is pivotally mounted about an axis 28. The vice 27 carries a lever arm 29 having a helically threaded through bore 30 40 into which extends a helically threaded member 31, which also extends through a helically threaded nut part 32 secured to base member 33. The helically threaded member 31 is provided with a handle 34 by means of which the helically threaded member 31 45 may be rotated causing pivotal movement of the second vice 26. Since the root end 24 of the turbine blade 10 is held in the vice 25, the turbine blade 10 will be twisted about its longitudinal axis and sufficient mechanical force is used to twist the 50 turbine blade 10 until it has the correct form after having been released from the vices 25 and 27.

It may sometimes be necessary to cause twisting of the turbine blade 10 at localised positions intermediate its ends 24 and 36. A modified apparatus 55 may be provided in which the vices 25 and 27 are movable towards and away from each other along an axis parallel with the turbine blade longitudinally, thereby enabling the blade 10 to be gripped at any two positions along its length.

After the application of such mechanical forces, the blade is subjected to heat treatment, for example as in the oven 60 shown in Figure 11, and then the form and shape of the blade may be checked by a gauge such as that shown in Figures 12 and 13.

The gauge shown in Figures 12 and 13 comprises

a base member 40 having a pair of upwardly extending support members 41 and 42, each of the members 41 and 42 being provided with horizontally aligned slots 43 and 44 respectively.

70 Extending between and located in each pair of horizontally opposed slots 43 and 44 are a pair of gauge members 45 and 46. Each of the gauge members 45 and 46 which comprise metal plates have a cut-out 47 and 48 respectively which corres-75 ponds to half the desired cross-sectional profile of the turbine blade 10 at a distance from the base member 40 determined by the distance from the base of the respective horizontally opposed channels 42 and 43.

In order to check if the turbine blade 10 is of the 80 correct form and shape, it is carefully positioned on the base member 40 and the gauge plate 45 and 46 inserted into their respective channels 42 and 43 and moved into contact with the turbine blade 10. If the gauge plates 45 and 46 do not fit around the turbine blade perfectly, i.e. there is a gap at any position between a gauge plate and the turbine blade, either the form or shape of the blade requires some correction, the form being corrected by imparting a 90 twisting force to the blade as afore-described, and the shape being corrected by the addition or removal of material by welding or grinding respectively for

After heat treatment the lacing wire holes 13 and 95 14 are reformed, for example by drilling. However, in normal circumstances the lacing wire holes will not be reformed until the turbine blade has been gauged and found correct in form and shape, since if it is not correct and further re-shaping and re-forming is 100 necessary.

Once again the turbine blade 10 will be subjected to heat treatment and if the form and shape is not correct, it will be subjected to mechanical forces to twist the turbine blade to the correct form and/or 105 machining, after which heat treatment will follow and the cycle of application of mechanical forces, heat treatment and measuring by the gauge will be continued until the gauged turbine blade is found to be correct.

110 The description of the method of the present invention of the method of the present invention describes each of the steps involved in the method of repair. However it will be appreciated that the apparatus illustrated, for example that for applying 115 mechanical forces to the blade to cause twisting thereof to return the turbine blade to its correct form, and the heat treatment oven, may be replaced by other methods of applying a twisting or bending force to the blade and oter forms of heat treatment 120 may be provided so long as they heat the blade sufficiently to cause relief of any residual stress.

CLAIMS

example.

1. A method of repairing a turbine blade of the 125 type having one or more lacing wire holes, the method comprising the steps of welding additional metal thereto, machining the repaired blade to the required shape and subjecting the blade to a stress

130 relieving heat treatment process, wherein prior to

the heat treatment process, the or each lacing wire hole is ffectively eliminated by filling the hole or holes with material which is the same as or at least is compatible with the material from which the blade is 5 made, and reforming, after the heat treating process, the or each of the holes.

- The method as claimed in Claim 1 wherein after the welding process has been carried out, the turbine blade is subjected to mechanical forces to
 restore it to its correct form and wherein the lacing wire hole or holes are filled prior to the application of said mechanical forces.
- 3. The method as claimed in Claim 1 or Claim 2 wherein the turbine blade is gauged by a gauging 15 apparatus prior to the heat treatment process.
- 4. The method as claimed in any one of the preceding claims wherein a portion of the turbine blade which is eroded or has been damaged is removed and a new piece of material is welded 20 thereto.
 - 5. The method as claimed in any one of Claims 1 to 3 wherein a damaged or eroded part of the turbine blade has metal added thereto in fused form by a welding process.
- 25 6. The method as claimed in any one of the preceding claims wherein the lacing wire hole or holes are each filled by a solid piece of material which is welded therein.
- The method as claimed in any one of Claims 1
 to 5 wherein the or each lacing wire hole is filled with metal in a fused condition by a welding process.

- 8. A method of repairing a turbine blade of the type having one or more lacing wir holes, the method comprising the steps of:-
- 35 (a) welding additional metal to an eroded or damaged part of the blade;
 - (b) filling the or each lacing wire hole with a metal the same as or compatible with the metal from which the turbine blade is made;
- 40 (c) gauging the blade to ascertain if it is of the correct form;
 - (d) applying mechanical forces to the blade to return it to its correct form;
- (e) subjecting the blade to a heat treatment45 process to relieve residual stress;
 - (f) machining the blade to return it to its correct shape;
 - (g) reforming the lacing wire holes.
- A turbine blade repaired in accordance withthe method as claimed in any one of the preceding claims.
 - 10. A method of repairing a turbine blade substantially as hereinbefore described with reference to and as illustrated in the accompanying drawings.
- 55 11. A turbine blade repaired in accordance with the method substantially as hereinbefore described with reference to and as illustrated in the accompanying drawings.
- 12. A method of repairing a turbine blade includ-60 ing any novel step or novel combination of steps as described in the specification and/or shown in the accompanying drawings.